



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: PT6A-27

Engine S/N: PC-E 41762

TTSN:	19,429.5
TCSN:	31,982.0
TSO:	2,556.1
CSO:	4,938.0
TSHSI:	89.6

P/N	Description	S/N	Total Cycles	FCF	Cycle Limit	Cycles Remaining
3013111	Hub	8D582	7,865	1	19,000	11,135
3013712	#2 Comp Disc	A000AHIA	12,955	1	24,000	11,045
3011713	#3 Comp Disc	4634	15,896	1	25,000	9,104
3013176	Impeller	7D457	8,184	1	19,000	10,816
3013411	CT Disc	6K503	10,635	1	16,000	5,365
3022412	PT Disc	A6835	14,124	1	20,000	5,876

Last Engine Overhaul by: Turbines, Inc.
Engine is fresh from repair and Test by Turbines Inc.
New PMA segments installed at repair
New PMA CT Blades installed at Overhaul.

Service Bulletins Complied with at Last Overhaul

1002, 1216, 1220, 1236, 1316, 1361, 1397, 1404, 1610

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: bgale@ctaerospace.com

dsmith@ctaerospace.com