



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: PT6A-28

Engine S/N: PC-E 40652

TTSN:	11,807.8
TCSN:	10,197.0
TSO:	0.0
CSO:	0.0
TSHSI:	0.0

P/N	Description	S/N	Total Cycles	FCF	Cycle Limit	Cycles Remaining
3013111	Hub	1Y761	4,512	1	19,000	14,488
3013712	#2 Comp Disc	8Y903	4,512	1	24,000	19,488
3011713	#3 Comp Disc	6553	10,197	1	25,000	14,803
3013176	Impeller	A3082	10,197	1	19,000	8,803
3013411	CT Disc	7A857	6,309	1	16,000	9,691
3022412	PT Disc	6R720	6,309	1	20,000	13,691

Overhaul performed by Avatas Engine Support Services

Contact: Bernie Gale

Title: Director of PT6/PW100 Engine Programs

Office Phone: 856-794-8222

Cell Phone: 856-466-2762

Email: bgale@ctaerospace.com

David Smith

President

972-241-1071

214-535-3687

dsmith@ctaerospace.com