



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: JT15D-5D

Engine S/N: PC-E 500073

TTSN:	4,842.4
TCSN:	2,346.0
TSO:	851.6
CSO:	612.0
TSHSI:	851.6
CSHSI:	612.0

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3041231	LC Hub	89A836	30,000	11,158	18,842
3054002-01	Booster Hub	A0010EH8	30,000	612	29,388
3040939	Impeller	A001CC33	12,000	612	11,388
3036411	HT Disc	A001D3WF	14,000	612	13,186
3022212	LT2 Disc	A000RH0M	14,000	4,036	8,632
3041593	LT3 Disc	A000P1KW	14,000	4,036	8,632
3117501-01	HT Blades	Various	On Condition	851.6 Hrs	N/A

Overhaul performed by PWWV Jul-03

Flight Count Factor is 1.33 to 1 for both LT Disc's and the HT Disc

Contact: Richard Hipp

David Smith

Title: Director of JT15D Engine Programs

President

Office Phone: 830-486-0520

972-241-1071

Cell Phone: 830-591-4777

214-535-3687

Email: rhipp@ctaerospace.com

dsmith@ctaerospace.com