



1615 Diplomat Drive, Suite 100  
Carrollton, Texas 75006

Phone: 972.241.1071  
Fax: 972.241.0073

Engine Model: PT6A-28

Engine S/N: PC-E 51974

Gas Generator:	51974
TTSN:	12,826.0
TCSN:	22,371.0
TSO:	3,841.3
CSO:	6,035.0
TSHSI:	1,226.4
CSHSI:	0.0

Power Section:	40,464.0
TTSN:	9,730.3
TCSN:	13,647.0
TSO:	3,951.1
CSO:	5,501.0
TSHSI:	N/A
CSHSI:	

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3013111	Hub	2T238	19,000	12,062	6,938
3013712	#2 Comp Disc	22A762	24,000	6,035	17,965
3011713	#3 Comp Disc	4T269	25,000	12,064	12,936
3013176	Impeller	4D619	19,000	6,035	12,965
3013411	CT Disc	5D927	16,000	8,163	7,837
3022412	PT Disc	2H012	20,000	11,713	8,287

**Lightning Strike Repair complied with by DAI 1998**

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: [bgale@ctaerospace.com](mailto:bgale@ctaerospace.com)

[dsmith@ctaerospace.com](mailto:dsmith@ctaerospace.com)