



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: PT6A-114A

Engine S/N: PCE-PC0769

TTSN:	4,959.8
TCSN:	6,851.0
TSO:	958.8
CSO:	1,057.0
TSHSI:	958.8

P/N	Description	S/N	Total Cycles	FCF	Cycle Limit	Cycles Remaining
3013111	Hub	63B661	6,851	1	19,000	12,149
3013712	#2 Comp Disc	A0009C5Y	6,851	1	24,000	17,149
3011713	#3 Comp Disc	A0009B5X	6,851	1	25,000	18,149
3027798	Impeller	A3082	6,851	1	19,000	12,149
3013411	CT Disc	A0009F7N	6,851	1	16,000	9,149
3026812	PT Disc	A001Y70B	1,057	1	20,000	18,943

Engine Overhauled by: Standard Aero. Fresh Compressor repair and test by PWC

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: bgale@ctaerospace.com

dsmith@ctaerospace.com