



1615 Diplomat Drive, Suite 100  
Carrollton, Texas 75006

Phone: 972.241.1071  
Fax: 972.241.0073

Engine Model: PT6A-41

Engine S/N: PC-E 80686

TTSN:	11,729.9
TCSN:	11,124.0
TSO:	0.0
CSO:	0.0
TSHI:	N/A
CSHI:	N/A

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3021911	Hub	A4308	20,000	11,124	8,876
3023112	#2 Comp Disc	A4465	20,000	11,124	8,876
3023113	#3 Comp Disc	8M219	20,000	7,684	12,316
3017463	Impeller	B1335	20,000	11,124	8,876
3024711	CT Disc	6L590	20,000	6,350	13,650
3029312	PT Disc #1	1T155	30,000	5,759	24,241
3029313	PT Disc #2	1A407	30,000	9,934	20,066

**Engine Overhauled by: Avatas Engine Support Services**  
**New CT Blades installed at overhaul.**

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: [bgale@ctaerospace.com](mailto:bgale@ctaerospace.com)

[dsmith@ctaerospace.com](mailto:dsmith@ctaerospace.com)