



CT Aerospace

1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: JT15D-5

Engine S/N: PC-E 100076

TTSN:	9,028.9
TCSN:	7,565.0
TSO:	1,939.3
CSO:	1,261.0
TSHSI:	168.3
CSHSI:	0.0

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3036811	LC Hub	3R104	12,000	7,565	4,435
3034112	Booster Hub	2R403	14,000	7,565	6,435
3033682	Impeller	4C776	9,000	7,565	1,435
3036411	HT Disc	25B227	14,000	6,097	7,903
3022212	LT2 Disc	2R905	14,000	7,565	6,435
3036113	LT3 Disc	3R000	14,000	7,565	6,435
3029601	HT Blades	Various	On Condition	N/A	On Condition

Last overhaul performed by: Bizjet

Contact: Richard Hipp

David Smith

Title: Director of JT15D Engine Programs

President

Office Phone: 830-486-0520

972-241-1071

Cell Phone: 830-591-4777

214-535-3687

Email: rhipp@ctaerospace.com

dsmith@ctaerospace.com