



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: JT15D-4B

Engine S/N: PC-E 102323

TTSN:	3,537.2
TCSN:	3,367.0
TSO:	0.0
CSO:	0.0
TSHSI:	0.0
CSHSI:	0.0

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3018018	LC Hub	4W677	27,500	6,734	20,766
3021112	Booster Hub	4W098	14,000	3,367	10,633
3036624	Impeller	8C593	8,200	3,367	4,833
3023411	HT Disc	781	14,000	3,367	10,633
3022212	LT2 Disc	PA2855	14,000	3,367	10,633
3021213	LT3 Disc	232	14,000	3,367	10,633
3029601	HT Blades	N/A	N/A	On Condition	On Condition

Last Overhaul performed by H&S Aviation May-07

Contact: Richard Hipp

David Smith

Title: Director of JT15D Engine Programs

President

Office Phone: 830-486-0520

972-241-1071

Cell Phone: 830-591-4777

214-535-3687

Email: rhipp@ctaerospace.com

dsmith@ctaerospace.com