



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: PT6A-28

Engine S/N: PC-E 51816

TTSN:	3,644.4
TCSN:	3,603.0
TSO:	0.0
CSO:	0.0
TSHSI:	0.0

P/N	Description	S/N	Total Cycles	FCF	Cycle Limit	Cycles Remaining
3013111	Hub	1B026	3,603	1	19,000	15,397
3013712	#2 Comp Disc	4A916	3,603	1	24,000	20,397
3011713	#3 Comp Disc	8A950	3,603	1	25,000	21,397
3013176	Impeller	2A383	3,603	1	19,000	15,397
3013411	CT Disc	A9143	1,739	1	16,000	14,261
3022412	PT Disc	3A150	3,603	1	20,000	16,397

Engine Overhauled by: Avatas Engine Support Services

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: bgale@ctaerospace.com

dsmith@ctaerospace.com