



1615 Diplomat Drive, Suite 100
Carrollton, Texas 75006

Phone: 972.241.1071
Fax: 972.241.0073

Engine Model: PT6A-41

Engine S/N: PC-E 80667

TTSN:	12,048.4
TCSN:	11,492.0
TSO:	0.0
CSO:	0.0
TSHI:	0.0
CSHI:	0.0

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3023611	Hub	A4267	20,000	11,492	8,508
3023112	#2 Comp Disc	A4445	20,000	11,492	8,508
3023113	#3 Comp Disc	B6608	20,000	11,492	8,508
3017463	Impeller	B1287	20,000	11,492	8,508
3041431	CT Disc	40B866	10,000	2,210	7,790
3029312	PT Disc #1	A0024PKR	30,000	315	29,685
3029313	PT Disc #2	9X343	30,000	5,062	24,938

Engine Overhauled by Avatas Engine Support Services

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: bgale@ctaerospace.com

dsmith@ctaerospace.com