



1615 Diplomat Drive, Suite 100  
Carrollton, Texas 75006

Phone: 972.241.1071  
Fax: 972.241.0073

Engine Model: PT6A-41

Engine S/N: PC-E 80715

TTSN:	11,943.5
TCSN:	11,325.0
TSO:	0.0
CSO:	0.0
TSHI:	0.0
CSHI:	0.0

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3021911	Hub	A4677	20,000	11,325	8,675
3023112	#2 Comp Disc	A4545	20,000	11,325	8,675
3023113	#3 Comp Disc	B6712	20,000	11,325	8,675
3017463	Impeller	B0564	20,000	11,325	8,675
3024711	CT Disc	A2648	20,000	11,325	8,675
3029312	PT Disc #1	26A137	30,000	3,820	26,180
3029313	PT Disc #2	9X337	30,000	4,857	25,143

**Engine Overhauled by Avatas Engine Support Services**

Contact: Bernie Gale

David Smith

Title: Director of PT6/PW100 Engine Programs

President

Office Phone: 856-794-8222

972-241-1071

Cell Phone: 856-466-2762

214-535-3687

Email: [bgale@ctaerospace.com](mailto:bgale@ctaerospace.com)

[dsmith@ctaerospace.com](mailto:dsmith@ctaerospace.com)